



Vermilion Bay Water Treatment & Distribution Systems

Problem: **Alarm System Failure**

Contact Info: Overall Responsible Operator (ORO)
Operator-In-Charge (OIC)

- Procedures:**
1. Notify the ORO and OIC immediately.
 2. Check 120 V power supply to the autodialer and phone line connections.
 3. Check SCADA computer setpoints and alarm enable/disable features.
 4. Check the PLC alarms setpoints.
 5. For PLC or SCADA failure, contact a representative of Selog at:
 6. If the autodialer failure remains unresolved, contact the Drinking Water Inspector for instructions.
 7. Frequent supervision of the plant will be required until the problem is resolved. In the past, the MOE has required plant check-ups every four hours or more frequently as directed by Drinking Water Inspector(s).