



CONTINGENCY PLAN Municipality of Machin

Machin 09-10

Vermilion Bay Water Treatment & Distribution Systems

Page 1 of 1

Problem: Standby Power Failure

Contact Info: Overall Responsible Operator (ORO)
Operator-In-Charge (OIC)

- Procedures:**
1. Immediately notify the ORO and OIC.
 2. Check generator status on the generator control panel. Verify it is in auto mode and whether or not the emergency stop is depressed.
 3. Check for the presence of alarms on the generator control panel (i.e. 'overtemp', 'overspeed', 'oil pressure').
 4. After troubleshooting the cause of the alarm (refer to O & M manual), try resetting alarms where present.
 5. Check the batteries and all the connections to the diesel.
 6. Check fuel tank level.
 7. If the generator still will not start in automatic mode, try manually starting the generator.
 8. Inform the ORO and OIC, and contact the manufacturer and/or an electrician.